
# **Flat Black Solid Brass Sheet**



### **FLAT BLACK SOLID BRASS SHEET - Laser Engraving**

#### C2015





# **GENERAL LASER ENGRAVING PROCESS**

## **Recommended Equipment & Accessories**

- CO2 Laser Engraver
- Clean Towel
- Isopropyl Alcohol

Recommended Settings- Laser Engraving	
50-60W lasers	
Laser Power	20-30%
Laser Speed	70-80%
Resolution (DPI/PPI)	500-600 DPI

#### **General Laser Engraving Instructions**

- Place the sheet onto the laser bed and align to the zero point on the laser bed.
- Adjust the laser focus to the surface of the sheet.
- For best results, turn air assist OFF (if equipped).
- Once the artwork is positioned, engrave using the suggested starting settings.
  - o Settings may need adjusted depending on the laser tube wattage.
- When finished, remove the sheet from the laser bed.
- If cleanup is needed, wipe the surface with a clean cotton cloth lightly misted with isopropyl alcohol.
  - o This sheet cannot be cut with a standard CO2 laser (under 100+ watts).

## **Troubleshooting**

- The engraving is not removing the black top layer.
  - o Laser power setting and/or resolution may need to be increased.
  - o Laser speed setting may need to be decreased.
  - o Check laser focus.
  - o Check and clean laser lenses and mirrors.
  - o Check laser alignment. (see laser users manual on how to check and adjust laser beam alignment)
- The engraving is darkening the brass metal finish under the black top coating.
  - o Laser power setting and/or resolution may need to be decreased.
  - o Laser speed setting may need to be increased.
  - o If air assist is equipped and is running, it may need to be turned off.

#### **Templates and Images**

• Visit jpplus.com to find the product page for this item. The product template may be found under the Tech Docs and Downloads area of the page.

To order more of this product, see similar products and much more, please visit JPPlus.com.

For additional product support and troubleshooting, please contact JPPlus Advanced Support Team:

- Phone: 419-500-4877
- Email: <u>ast@jpplus.com</u>
- Schedule an appointment: jpplusadvancedsupport.setmore.com/