



SAFETY DATA SHEET

SDS No: 0050

Section 1. Product and Company Identification

Product Name: Colorshop Woods

Trade Name: Baltic Birch Plywood

Recommended Use: Signage, Other

Restrictions on Use: None

Manufacture: Rowmark
5409 Hamlet Drive
Findlay, OH 45840

In Case of Emergency: Call: Medical: 911
Poison Control: 800-589-3897

Information: Call: 1-877-ROWMARK
Email: techhelp@rowmark.com

Section 2. Hazard Identification

GHS Classification: Not Classified

GHS Label Elements: Not Applicable

GHS Rating

Health	5
Flammability	4
Instability	5
Other	

Other Hazards: Not Applicable

NEW GHS Hazard Categories

Category 1 = Severe Hazard

Category 2 = Serious Hazard

Category 3 = Moderate Hazard

Category 4 = Slight Hazard

Category 5 = Minimal Hazard

Section 3. Composition / Information on Ingredients

Name	CAS #	% by Weight
Birch Veneer	N/A	90-100%
Glue: Adhesive Bond for Veneer		
Carbamide Formaldehyde Resin	9011-05-6	Trace Levels
Lignosulfonates (provides viscosity)	8061-51-6	Trace Levels
Kaolin (provides viscosity)	1332-58-7	Trace Levels
Ammonium Chloride (hardener)	12125-02-9	Trace Levels
Lacquer Sealer		
n-Butyl Acetate	123-86-4	Trace Levels
Acetone	67-64-1	Trace Levels
Methanol	67-56-1	Trace Levels
2-Propanol	67-63-0	Trace Levels

* Remaining components are proprietary, non-hazardous, and/or present at amounts below reportable limits.

Section 4. First Aid Measures

Inhalation:	Dust and process vapors may be irritation to the nose, throat and respiratory tract. Remove to fresh air. If not breathing, give artificial respiration. If breathing is difficult, give oxygen. Get Medical attention.
Eyes:	Dust, fines and process vapors may irritate the eyes. Immediately flush eyes with water for at least 15 minutes. Get medical attention.
Skin:	Wash affected areas with soap and water. Get medical advice if rash or persistent irritation or dermatitis occurs.
Ingestion:	Not applicable.

Section 5. Fire-Fighting Measures

Suitable Extinguishing Methods:	Dry Chemical, Water Spray, Foam Carbon Dioxide, Sand
Hazards During Fire-fighting:	Carbon monoxide, carbon dioxide, original monomer other hydrocarbon oxidation products.
Protective Equipment:	Wear self-contained breathing apparatus and protective suit.

Section 6. Accidental Release Measures

Personal Precautions:	See Section 8 - Exposure Controls / Personal Protection.
Environmental Precautions:	No Special environmental precautions required.